



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D205-634-011
Job Sheet 173701



Part No: D205-634-011

Job Qty: 1 ea

Part Name: Skidtube with Standard Wearplates Fits LH or RH



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 3/6/18

Job Tracking No:

Due Date: 3/30/18

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV I SHEET 11 IPP Rev:P 02.08.28 Removed QC5 from Step 5 KJ IPP Rev:Q 08-08-12 now @ chg 006 (DSI 9417) DD ver:EC IPP Rev R 09.01.28 now chg 007 DSI9417 revB EC ver:DD IPP Rev:S 10.12.01 as per chg008 DD ver:EC IPP REV:T 12.01.23 AS PER ECN11-684 VERF:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	3/30/18	3/30/18	0.00	0.00	Start Up Stores/Pkg-1		SMB
110	Packaging	1 pcs	3/30/18	3/30/18	0.00	0.00	Packaging1-2		SMB
120	QC	1 pcs	3/30/18	3/30/18	0.00	0.00	QC4		M. D.
125	DC	1 pcs	3/30/18	3/30/18	0.00	0.00	DC		M. D.
130	Packaging	1 pcs	3/30/18	3/30/18	0.00	0.00	Packaging3-1		M. D.
140	QC21-FG	1 Ea	3/30/18	3/30/18	0.00	0.00	QC21		

Part Op 125 - Photocopy bluefile & type labels per PPP D205-634-011 CHG 011

Descriptions: 130 - Identify and pack for shipping as per PPP D205-634-011 Location: FG084

DAS
21
9-80

APR 18 2018

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D205-634-041	Replacement Skidtube with Standard Wearplates Fits LH or RH	1 Ea (1 ea)	90-Start up Operation	5056607
K10003	Saddles	1 Ea (1 ea)	90-Start up Operation	3099573

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D205-634-041	1	7	0
	K10003	1	1	0

Part Specifications

Specifications could not be found.

Plex 3/6/18 1:02 PM Dart.lajeunesse.marie

5056607

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____ Date : _____ Descripti _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Skid-tube ☐ Machining ☐ Thermoforming ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging Supplier ☐ Engineering ☐ Quality ☐ Other ☐	AGAINST DEPARTMENT/PROCESS Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging Supplier ☐ Engineering ☐ Quality ☐ Other ☐
		MRB (QSI042) Approval
		Completed By
		Lead hand / Supervisor Approval Verification
		QC / QA Coordinator Approval

DART Aerospace Ltd.
1270 Aberdeen Street
Lawrenceburg, TN 38464
Tel: 615 892-5200
Email: sales@dartaero.com
www.dartaero.com

Container No: S062398

Part: D205-634-011
Job No: 173701
Serial No/Batch: S062398

Date: 04/18/18

Root Cause			
Environment	☐	No Re-ve	☐
Design	☐	Operator	☐
Doc/Data	☐	Offset/Setu	☐
Equip/Tooling	☐	Supplier	☐
Handling/Pre	☐	Training	☐
Material	☐	Use for Testing	☐
Internal Transport	☐	Poor Information	☐
Tribal Knowledge	☐	Rushing	☐
LOA	☐	Product Improvement	☐
Substation	☐	Process Improvement	☐
Past Expiry Date	☐	Manufacturing Process	☐
Misidentified	☐	Past Due	☐

OTHER : _____

PAGE 1 OF 1

Description: SKIDTUBE w/ STANDARD WEARPLATES, LH/RH

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					